

## SALES QUOTATION

VAT No . 220011772900002

<b>To : INTERLOCK MAINTENANCE CONSTRUCTION W.L.L</b>	<b>Date : 28-Mar-2026</b>
Flat : 310, Bld : 1501, Rd : 2116, Blk : 321 Area : Gudaibiya , Kingdom of Bahrain Tel : +973 17296175 , VAT No : 200010671200002	<b>Quot No. : SQ001981</b>

**Subject:** Carpentry works Al noor

**Attention:** , Mob:

Dear Sir/Madam,

Reference to your enquiry, in connection with the aforementioned subject, with pleasure we are quoting hereunder our price and other terms and condition towards the scope of work specified herein below, for your kind approval.

### (A) Description of work.

SINo	Description	Qty	Unit	Price	Amount
1	Ref 4 - G14 Replace damaged 45mm thick single door shutter flush type (D-2) covered by 6mm thick external quality plywood facing to both sides complete with door lock ( plate type ) & hinges, stopper, kicker plates including the provision of smaller size vision panel and finish with gloss paint matching to the existing. (No louver panel), see attached Drawing no.09	11	No	175.000	1,925.000
2	Ref 5 - G16 Replace damaged 45mm thick single door shutter flush type (D-4) covered by 6mm thick external quality plywood facing to both sides complete with door lock ( Plate Type ) & hinges, stopper, kicker plates including the provision of louver panel and finish with gloss paint matching to the existing. (No vision panel), see attached Drawing no.11	7	No	200.000	1,400.000
3	Ref 6 - G36 Repair single / double door frame by minor patch up of the damaged area and complete with paint.	16	No	50.000	800.000
4	Ref 7 - G20A Replace damaged 45mm thick double door shutter flush type (D-8) ex. 1500mm wide covered by 6mm thick external quality plywood facing to both sides complete with door lock ( plate type ), hinges & tower bolts including the provision of vision panel to main door and finish with gloss paint matching to the existing. (No louver panel), see attached Drawing no.15	1	No	225.000	225.000
5	Ref 32 - G02 Replace damaged door frame for single door of size	35	No	100.000	3,500.000

	50mm x 150mm without transom fix with sufficient screws and complete with paint matching to the existing				
6	Ref 33 - G14 Replace damaged 45mm thick single door shutter flush type (D-2) covered by 6mm thick external quality plywood facing to both sides complete with door lock ( plate type ) & hinges, stopper, kicker plates including the provision of smaller size vision panel and finish with gloss paint matching to the existing. (No louver panel), see attached Drawing no.09	35	No	150.000	5,250.000
7	Ref 34- G36 Repair single / double door frame by minor patch up of the damaged area and complete with paint.	33	No	50.000	1,650.000
8	Ref 35- G38 Repair single/ double door shutter by minor patch up to the damaged area and complete with paint	6	No	70.000	420.000
9	Re 36 - G42 Take down, repair & re-fix door shutter by replacing the damaged 1.5mm thick laminated sheets to both sides including hardwood lipping and complete with paint	108	Sq. Meter	25.000	2,700.000
10	Ref 37- G81 Replace damaged overhead door closer (heavy)	35	No	30.000	1,050.000
11	Ref 38 - G83 Replace damaged door butt hinges	75	No	6.000	450.000

**Sub Total : 19,370.000**

**Taxable Amt : 19,370.000**

**VAT (10%) : 1,937.000**

**Net Amount : 21,307.000**

**TWENTY-ONE THOUSAND THREE HUNDRED SEVEN ONLY**

**Account Name: SNV PUBLICITY AND ADVERTISING CO. W.L.L.**  
**Account No.: 0005 303327 001 Account Type : MA CURRENT ACCOUNT**  
**IBAN No: BH54AUBB00005303327001**  
**SWIFT CODE: AUBBBHBM**

Yours Faithfully,  
**For SNV PUBLICITY & ADVERTISING**



Prepared By,  
**Dileep**